

0855Z 20 JAN 63

S E C R E T

25X1 DIRECTOR

OSA (1,2,3,4,5,6,7,8,9,10,11,12,13,14,15,16)

S/C (17)

TOR 1125Z 20 JAN 63

PRIORITY

25X1 IN 63109

25X1 PRITY

25X1 NO NITE ACTION

25X1 1. POST FLIGHT FINDINGS MISSION

3213/190140/342.

25X1 2. "X" AND "S" BANDS MASTER RECORDER, OPERATED WITH ONE AND LESS THAN TWO DBM TRANSSSENTUAL. NOISE, SATURATION AND VOLTS REMAIN THE SAME.

25X1 3. "L" AND "P" BAND SLAVE RECORDER, NO CHANGE THAT WHAT HAS BEEN REPORTED ON PRE-FLIGHT DATA SHEET WITH TAPES SENT HQS.

25X1 4. OPERATED WELL THROUGH OUT MISSION.

25X1 5. ALL RECORDERS, TONES ON RECORDERS, AND SWITCHING TIMES OPERATED PROPERLY.

25X1 6. UNABLE TO DETERMINE REASON FOR NO SIGNALS ON

25X1 PLAN TO RUN TEST HOP ASAP.

END OF MESSAGE

S E C R E T

25 YEAR RE-REVIEW

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy 115